

Specification

| | |
|----------------|-----------|
| Stock No | 688632 |
| Type | 4 WAY |
| Make | COMBILIFT |
| Model | C5000XL |
| Year | 2019 |
| Euromast | 2F402 |
| Hours | 1461 |
| Capacity | 5000 kg |
| Lift height | 4020 |
| Values | |
| Quality Rating | 4 |

Mechanical

| | |
|---------------------------------|--------|
| Character. | |
| Load Centre (c) | 600 mm |
| Operating mode (Characteristic) | Seated |

Weights

| | |
|--------------------------------|---------|
| Service weight (Total weight) | 7100 kg |
|--------------------------------|---------|

Wheels

| | |
|-----------------------|--------------|
| Tyres type | Superelastic |
| Tyres front condition | 50% |
| Tyres rear condition | 50% |

Dimensions

| | |
|---------------------------------------|----------------|
| Lift height (h3) | 4020 mm |
| Extended height (h4) | 4930 mm |
| Height of overhead guard (cabin) (h6) | 2550 mm |
| Overall length (l1) | 2500 mm |
| Length to fork face (l2) | 1300 mm |
| Overall width (b1/b2) | 2430 mm |
| Forks length (l) | 1200 mm |
| Fork carriage (class) | DIN 15173 / 3A |
| Fork carriage width (b3) | 1370 mm |
| Length of chasis (l7) | 2470 mm |
| Collapsed height (h1) | 2900 mm |
| Forks height (s) | 50 mm |
| Forks width (e) | 150 mm |
| Auxiliary lift (h9) | 2025 mm |

Performance

| | |
|---------------|-------------|
| Service brake | hydrostatic |
|---------------|-------------|

Drive

| | |
|--------------------------|----------|
| Battery voltage/capacity | 12V V/Ah |
|--------------------------|----------|

Attachment

| | |
|------------------------------|----------------------|
| Attachments (Has attachment) | Sideshift and forks. |
|------------------------------|----------------------|

Engine

| | |
|-----------------------------|----------------|
| Manufacturer of engine/type | Kubota V2403-T |
| Engine type (Engine type) | diesel |

Location

Extras

| | |
|-------------|-------------------------------------|
| Extras | SS, Full Cab, Lights, Heater, Fans. |
| Extras Hyds | 3rd & 4th |

Visual



Appearance: Very good cosmetic condition.
Mechanical Status: Very good working order
More: [Click here for more photos](#)

