

Specification

Stock No	329312
Type	DIESEL
Make	LINDE
Model	H40D
Year	2013
Euromast	3F586
Hours	14150
Capacity	4000 kg
Lift height	5860
Values	3
Quality Rating	4

Mechanical

Character.	
Load Centre (c)	500/600 mm
Operating mode (Characteristic)	Seated
Wheelbase (y)	1998 mm

Weights

Service weight (Total weight)	6280 kg
Axle load with load (front/rear)	8610/1180 kg

Wheels

Tyres type	Superelastic
Tyres front condition	10%
Tyres rear condition	10%
Tyre size front	250-15-SC15 mm
Tyre size rear	250-15-SC15 mm
Track width front (b10)	1221 mm
Track width rear (b11)	1122 mm

Dimensions

Lift height (h3)	5860 mm
Extended height (h4)	7045 mm
Height of overhead guard (cabin) (h6)	2400 mm
Overall length (l1)	4200 mm
Length to fork face (l2)	3000 mm
Overall width (b1/b2)	1446 mm
Forks length (l)	1200 mm
Fork carriage (class)	DIN 15173 / 3A
Fork carriage width (b3)	1350 mm
Ground clearance, mast (m1)	158 mm
Ground clearance, centre of wheelbase (m2)	201 mm
Turning radius (Wa)	2672 mm
Ast across 1000x1200 (Ast)	4355 mm
Ast along 800x1200 (Ast)	4555 mm
Towing coupling height (h10)	703 mm
Collapsed height (h1)	2760 mm
Seat/stand height (h7)	1226 mm
Forks height (s)	50 mm
Forks width (e)	120 mm
Auxiliary lift (h9)	2050 mm

Performance

Travel speed (With, w/o load)	21 km/h
Lifting speed (With, w/o load)	0.53/0.56 m/s
Lowering speed (With, w/o load)	0.52/0.57 m/s
Climbing ability (30 min rating - with, w/o load)	29/34 %
Acceleration time (With, w/o load)	5.5/4.8 sec
Service brake	hydrostatic

Drive

Drive motor (60 min rating)	55 kW
Battery voltage/capacity	12V V/Ah

Other

Noise level	79 dB
Working pressure	170 bar
Oil flow (For attachments)	48 l/min
Traction control	HYDROSTATIC TRANSMISSION

Attachment

Attachments (Has attachment)	Sideshift and Forks.
Attachment type (Attachment type)	Sideshifts

Engine

Manufacturer of engine/type	VW / AUDI
Engine rated power (ISO 1585)	53 kW
Rated rpm	2800 rpm
Cylinders/Displac. ccm	4/1896
Fuel consumption (VDI)	4.6 l/h
Engine type (Engine type)	diesel

Opinion

Location

Extras

Extras	SS, Lights, Blue Spots.
Extras Hyds	3rd

Visual



Appearance: Very good appearance for age, ripped seat.

Mechanical Status: Very good working order

More: [Click here for more photos](#)

