

Specification

| | |
|----------------|-------------|
| Stock No | 338120 |
| Type | GAS |
| Make | LINDE |
| Model | H16T-01 391 |
| Year | 2017 |
| Euromast | 2W315 |
| Hours | 16128 |
| Capacity | 1600 kg |
| Lift height | 3150 |
| Values | 3 |
| Quality Rating | 3 |

Mechanical

| | |
|---------------------------------|--------|
| Character. | |
| Load Centre (c) | 500 mm |
| Operating mode (Characteristic) | Seated |

| | |
|--------------------------------|---------|
| Weights | |
| Service weight (Total weight) | 3050 kg |

| | |
|-----------------------|--------------|
| Wheels | |
| Tyres type | Superelastic |
| Tyres front condition | 90% |
| Tyres rear condition | 90% |

| | |
|---------------------------------------|----------------|
| Dimensions | |
| Lift height (h3) | 3150 mm |
| Extended height (h4) | 4150 mm |
| Height of overhead guard (cabin) (h6) | 2120 mm |
| Overall length (l1) | 3350 mm |
| Length to fork face (l2) | 2350 mm |
| Overall width (b1/b2) | 1100 mm |
| Forks length (l) | 1000 mm |
| Fork carriage (class) | DIN 15173 / 2A |
| Fork carriage width (b3) | 980 mm |
| Length of chassis (l7) | 2170 mm |
| Collapsed height (h1) | 2130 mm |
| Forks height (s) | 40 mm |
| Forks width (e) | 100 mm |

| | |
|---------------|-------------|
| Performance | |
| Service brake | hydrostatic |

| | |
|-----------------------------|----------|
| Drive | |
| Drive motor (60 min rating) | 28 kW |
| Battery voltage/capacity | 12V V/Ah |

| | |
|-----------------------------------|----------------------|
| Attachment | |
| Attachments (Has attachment) | Sideshift and Forks. |
| Attachment type (Attachment type) | Sideshifts |

| | |
|-------------------------------|--------------|
| Engine | |
| Manufacturer of engine/type | VW / AUDI |
| Engine rated power (ISO 1585) | 28 kW |
| Cylinders/Displac. ccm | 4 Cylinders. |
| Engine type (Engine type) | gas |

Location

| | |
|-------------|--------------------------------------|
| Extras | |
| Extras | SS, Half Cab, LED Lights, Blue Spot. |
| Extras Hyds | 3rd |

Visual



Appearance: Very good appearance for age

Mechanical Status: Very good working order

More: [Click here for more photos](#)

