



Stock No 327209 Туре DIESEL Make LINDE Model H40D-02 394 Year 2015 Euromast 2W370 17667 Hours Capacity 4000 kg Lift height 3700 Values 3 Quality Rating 3

Mechanical

Character Load Centre (c) 500/600 mm Operating mode (Characteristic) Seated Wheelbase (y) 1998 mm

Weights

Service weight (Total weight) 5985 kg Axle load with load (front/rear) 8610/1180 kg

Wheels

Superelastic Tyres type Tyres front condition 20% Tyres rear condition 25% Tyre size front 250-15-SC15 mm Tyre size rear 250-15-SC15 mm Track width front (b10) 1221 mm Track width rear (b11) 1122 mm

Dimensions

Lift height (h3) 3700 mm Extended height (h4)
Height of overhead guard (cabin)
(h6) 4320 mm 2400 mm Overall length (I1) 4200 mm Length to fork face (I2) 3000 mm Overall width (b1/b2) 1446 mm Forks length (I) 1200 mm DIN 15173 / 3A Fork carriage (class) Fork carriage width (b3) 1745 mm Ground clearance, mast (m1) Ground clearance, centre of wheelbase (m2) 158 mm 201 mm 2672 mm Turning radius (Wa) Ast across 1000x1200 (Ast) 4355 mm Ast along 800x1200 (Ast) 4555 mm Towing coupling height (h10) 703 mm Collapsed height (h1) 2720 mm Seat/stand height (h7) 1226 mm Forks height (s) 50 mm Forks width (e) 120 mm

Performance

Travel speed (With, w/o load) 21 km/h Lifting speed (With, w/o load) 0.53/0.56 m/s Lowering speed (With, w/o load) Climbing ability (30 min rating -with, w/o load) 0.52/0.57 m/s 29/34 % 5.5/4.8 sec Acceleration time (With, w/o load) Service brake hydrostatic

Drive

Drive motor (60 min rating) 55 kW Battery voltage/capacity 12V V/Ah

Other

Noise level 79 dB Working pressure 170 bar Oil flow (For attachments) 48 l/min HYDROSTATIC Traction control TRANSMISSION

Attachment

Attachments (Has attachment) Sideshift and Forks. Attachment type (Attachment type) Sideshifts

Engine

Manufacturer of engine/type VW / AUDI Engine rated power (ISO 1585) 53 kW Rated rpm 2800 rpm Cylinders/Displac. ccm 4/1896 Fuel consumption (VDI) 4.6 l/h Engine type (Engine type) diesel

Opinion

Location Extras

SS, Full Cab, Air-Con, LED Lights. Extras Extras Hvds 3rd



Appearance: Scruffy

Mechanical Status: Not tested

More: Click here for more photos







